

# VEHICLE INSPECTION REPORT

**DK66KAX**

## Man TGS 26.360

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date 23/01/2017

VIN WMA18SZZXHP083629

Axle Combi 6x2

Year 2017

Body Style Dropside & Crane

Steering Combi Rear-Lift Steer

Mileage 132,708 Km Warranted

MOT Due 30/11/2025

Rear Suspension Steel

Fuel Type Diesel

Cab Type DAY CAB

Colour BLUE

Gearbox MANUAL

HMF 1420 K2 REMOTE CRANE (YEAR 2016), SURROUND CAMERA SYSTEM, SERVICE SCHEDULE LIST AVAILABLE

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Park assist camera

## Photos










## Condition Check



## Damage Photos



1: Bumper Front Moulding  
Scuffed (Unpainted)  
UpTo 100mm



2: Fog Lamp Surround os  
Scuffed (Unpainted)  
UpTo 100mm



3: Wing osf  
Scratched  
UpTo 25mm Thru Paint



4: Screen Front  
Chipped  
UpTo 10mm



5: Bumper Front  
Cracked  
UpTo 25mm



6: Bumper Front Moulding  
Scuffed (Unpainted)  
UpTo 100mm



7: Fog Lamp Surround ns  
Scuffed (Unpainted)  
UpTo 100mm



8: Door Mirror Assy nsf  
Missing  
Replace





9: Door Mirror Assy nsf  
Scuffed (Unpainted)  
UpTo 100mm



10: Other  
N/A  
N/A



11: Other  
N/A  
N/A



12: Other  
N/A  
N/A



13: Qtr Panel nsr  
Dented  
Over 30mm



14: Bumper Rear  
Rusted  
Over 5mm





15: Qtr Panel osr  
Dented  
Over 30mm



16: Other  
N/A  
N/A



17: Other  
N/A  
N/A



18: Other  
N/A  
N/A



19: Other  
N/A  
N/A



20: Door Mirror Assy osf  
Scuffed (Unpainted)  
UpTo 100mm



21: Other  
N/A  
N/A

22: Door Pad osf  
Broken  
Replace

## Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Parking Brake	OK			Gearbox Static Gear Selection (engine running)	OK		
				No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		